



Nicht bemaßte Bohrungen: $\varnothing 4$

Drillings without measures: $\varnothing 4$

All measures are given

in Millimeters

Hakenblende - Hook shield